3645 Clay 400



Real Property Records

Date last updated: Friday, November 21, 2003

Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

Link to property tax information for this property

Link to property sales information for this neighborhood

Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential

Parcel: 0222205022000

Name and Address Information

Legal Description

PADILLA, ANDREW M

HORNES SUB 2ND FLG B1 L41 &

4463 CHEROKEE ST

DENVER, CO 80216

RESIDENTIAL

Property Address:

Tax District

4463 CHEROKEE ST

DENV

42

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	37100	2950		
Improvements	152700	12160		
Total	189800	15110	0	15110
Prior Year				
Land	19300	1770		
Improvements	117900	10790		
Total	137200	12560	0	12560

Style: One Story

Year Built: 1891

Building Sqr. Foot: 1,238

Bedrooms: 2

Baths Full/Half: 1/0

Basement/Finished: 574/0

Lot Size: 5,500

Zoning: I1

Reception No.: 0000072070

Recording Date: 04/17/03

Document Type: Personal Rep

Sale Price: 159900

Mill Levy: 59.855

#2447

Web Ticket Entry

Х

<> Ing New Update Test Cancel Reset Exit Ticket # 0000117817-000 has been queued!

Ticket 0000117817 Date 03/16/2004 Time 09:28AM

Oper JWL957208934

Rev 000 NEW GRID

Old Tkt 0000117817 Date 03/16/2004 Time 09:28AM

Oper **JWL957208934**

Chan WEB

Phone 303-487-0377 Ext

Caller JASON LYNCH

Email JLYNCH@PROJECTRESOURCESING.COM

Company PROJECT RESOURCES

Fax 303-295-0990

Address 10 E 55TH AVE

City **DENVER**

State CO Zip 80216

Alternate Contact TODD MYERS

Phone 3034870377

Ext

Done for CORPS OF ENGINEERS / EPA

Work type SOIL EXCAVATION TO A DEPTH OF 12 INCHES F

Explosives N Boring N

Meet time requested N

St CO Cnty DENVER

Place **DENVER**

Addr From 4463

Street CHEROKEE STREET

Nearest Intersecting Street

Latitude Longitude

Location ENTIRE RESIDENTIAL PROPERTY FROM THE CURB AT THE ADDRESS LISTED ABOVE - SOIL EXCAVATION TO A DEPTH OF 12 INCHES FROM ENTIRE PROPERTY.

The locate will be completed between 03/16/04 09:29:09 AM and the end of the day 03/18/2004

Grids (T/R/S) 03S068W22NW

Members CDOT06 CMSDC00 CMSND14 LVL311 MCLD01 PCND00 PSND14 QLNCND00 QLNCND14 QWST01

Members - these will be notified by the center

PCND00 XCEL ENERGY

XCEL ENERGY XCEL ENERGY---APPT FILE XCEL ENGY--APPT SCHEDULE-- UQ

PSND14 CMSDC00 COMCAST-CATV

COMCAST-CATV/UQ

OLNCND14 OWEST LOCAL NETWORK---APPT. SCHED. QWEST LOCAL NETWORK

QLNCND14	QWEST LOCAL NETWORKAPPT. SCHED.	QWEST LOCAL NETWORK
LVL311	LEVEL 3 COMMUNICATIONS	LEVEL 3 COMMUNICATIONS
MCLD01	MCLEODUSA (MCLEOD USA)	MCLEOD USA (FIBER)
QLNCND00	QWEST LOCAL NETWORK	QWEST LOCAL NETWORK (UQ)
QLNCND00	QWEST LOCAL NETWORK	QWEST LOCAL NETWORK (UQ)
CMSND14	COMCAST-APPT. SCHED.	COMCAST-CATV/UQ
PSND14	XCEL ENERGYAPPT FILE	XCEL ENGYAPPT SCHEDULE UQ
PCND00	XCEL ENERGY	XCEL ENERGY
CMSDC00	COMCAST-CATV	COMCAST-CATV/UQ
CMSND14	COMCAST-APPT. SCHED.	COMCAST-CATV/UQ
QWST01	QWEST COMMUNICATIONS	QWEST COMMUNICATIONS
CDOT06	COLO DEPT OF TRANSPORTATION, REGION 6	CDOTREGION 6

TIER2 MEMBERS - you must notify these members yourself

DTEO01	DENVER TRAFFIC ENGINEERING OPERATIONS	DNVR TRAFFIC ENG OPERAT.	720-865-4001
DNVH20	DENVER WATER DEPARTMENT	DENVER WATER DEPT	303-628-6666
MWRD01	METRO WASTEWATER RECLAMATION DISTR	METRO WASTEWATER RECLAM	303-286-3432
WWMG01	WASTEWATER MANAGEMENT DIVISION	WASTEWATER MGMT DIVISION	303-446-3744


Address: 4463 Cherokee	
Date: 16/5/04	
Investigator:	

Occupant: _____ Phone Number: _

House Garage Shed

_: North South East West

Painted S		Color	XRF	Total Area of Element	Percent Deteriorated	Deteriorated Area	Replacement Recommendations	Options
From of	Forch.	gruz	0.00 to,04	i j		None		
Porch Po	513	white	0.26 to.27			Nonz		
Brick V		white	(582) 4.3±1.	6 24' × 9'	210%	Very little cracking 2 2 fc 28	rio	notion tropart
lower i		din	5037 2.9±1.2.	31/21 x 2401	0%	None		ercup & repaint
Porch (V12 0.	white	(50 G) 9.5 I 2.7	19'x 71/2'		end of support	End boards Fuscia_ replace w/ gutter	
Nuclow	Frame	white	0.07+0.27	5+0 4'x 51/2' opering 2.750.8 2"Frame	0%	0%		
'n uncloses Calol Ho	50.5h	white		(cars benind 445/2' Siren				
dar Fra		white	(57 2) 5.8:2.2	2 x 5 1/2 x 2"	0%	Ö		
South 5 Porch - up	de oper wall	white	573 0.07±0.135	+31/2 x 5" EXT, 5 († 1.7. (574) 100.542	Jol 10			
2 garage a 2 trin a ander o	end to	Links	ו לשיבונין ווני ע	1/2×24'×9'		Trm 15"x 15"x(2)	Not herded.	
1 -1001107		whirte	507 1.11.3 -15± 15				belief to replace	replace + painted Rise
	cup Stone	White	(500) 11=3.5	15.25'l x 51/2" hx 9"W +512 x 51/2" \ 9"		9"x 36" + 9"x 9"		
porch 5	k45	grenz	(564) 0.0950.34					



4463 Cheroker

) Garage Shed ____ Address: Color **XRF** Total Area of Element Replacement **Options** Painted Surface Percent Deteriorated Recommendations Deteriorated Area

Address: 4463 Cherokee

House Gar

Shed ___

North

outh.

Ecrot

West.

Painted Surface	Color	XRF	Total Area of Element	Percent Deteriorated	Deteriorated Area	Replacement Recommendations	Options
gate end	White	assumed	24'x 10' x1/2 - 2x5 wndow	100/0		20 Shingles (wood shakes)	
back add. Two	white	no lead					
back Forch post back fence	white	579 0,00±0,61					
back fence	white	0.0010.08					
	 						
		:					
						•	

Address:

(House) Garage Shed

NoAm (South) East West

Painted Surface	Color	XRF	Total Area of Element	Percent Deteriorated	Deteriorated Area	Replacement Recommendations	Options
upper walto brukk	white	game as front	36/2/x 9/ - 3 usundonss 36/2x 1/21				
lower walls	grey	sine as Front	361/2 x 1/21				
Window screens frames (3)	white	576 0.0150.14	_	·			
Wordon Franco (3)	white	Jame	21/21 × 6' window 2" frome	L10 %			·
Window Sash (3)	w) FC	assumed		100%	trough to	Eld condons conto be replaced	
Bom windows	History/	إيسان وفي	3'41.25'	1000/16	inchede intro	could be replaced ap into cellar	() open & clean/repart
Back addition Sidms	white	577 0.005 0.01					
Buck add hon window from	wnite	578 0.0110.04					
						·	·
							,
						·	

Address: 4463 therokel Back house North South (Back House) Garage Shed -**Options** Painted Surface **XRF Total Area of Element** Replacement Color Percent Deteriorated Recommendations Deteriorated Area red 0,0210.25 Forch Ploor/ Stairs 581 582 tan porch posts 0.02 =0.12 583 porch ciren 0.0410.27 91/21x 1/2×8" Chimney-bnok 584 White 410% 3-512ed box 4,5+1.5 window Frame 585 red 0,02±0.14 white 31/2"x 71 x 2 corner born 586 (SE corner) B.250.7 Sofoit & rafter tails white 590 0:4550.22 Back House South South side 0.00 IO.10 white 5071it 588 much House wort (past corner trim Negative white (NE Corner) 4'x 4"x(2) window trim 594 3 wondows some high red NO None none 2.6 × 4" 58-2.0 Back House - west in alley - would chep into all

brick well

0.05t 0,28

600


white


assume all undow trim hot to windows + att 3 in Alley (right up on any would this mes along)


Address: 4463 Chevokee

House Garage Shed Shackyard

Painted Surface Color **XRF Total Area of Element** Deteriorated Replacement Options Percent Deteriorated Area Recommendations 0.05 to.12 white 598 0.02±0.10 Neighbors garage 599 While









Daily Quality Control Report **VB/I-70** Lead Based Paint Assessment

Date: 07-19-66

Property Location 44

Type at	nd Location of	Tests Per	formed and	Results					
र १९५५) स्रोत	May a faller	1. 40°	a and	mifreduis)ic j	म् अन्यक्षास्य को देखाँगी । करवा	Habletegeniet.	्रोंचू तार मार्क्के	shooter	(6(3)(5)+6
2447	1878		0.18	E.	pach column N.E.	Intact Cracked Chipped Peeling		Brick	white
	1879		0.00	E.	posch wall	Intact Cracked Chipped Peeling		COCCACT	white
	1880	4.6		B.1	posch wall cap		814/0	White	TAN
	1881		1.03	E. '	DOACH WAS	Intact Cracked Chipped Peeling		CONCRETE	grey
	1882	9.8		E. '	N.W. WOOD 2 ROOMS	Intact Cracked Chipped Peeling Intact Cracked	3"X 31	was	white
	1883		0.09	E.	South size youth steps	Chipped Peeling		CONNEC	9 Dec
	1884		0.02	61	INSME pouch wall Free	Chipped Peeling		white	white
	1885	4.5		E	South side soffit	Chinped Peeling	1"X5"	W000	white
	1886		0.7	E,	FASCIA BOARD GABLE	Chipper Peeling			white
	1887		0.7	E.	FASIA BOARD GABLE	Intact Cracked Chipper Peeling Intact Cracked			white
	1888	2.3		E.	WYLDOW FAMILYE CABLE	Chipped Peeling	<u>31/441</u>	wood	whire
	1889			E.	shivale Null	Chipped Pecling Intact Cracket			
	1890	1.5		8.	GASTE Shingle	Chippen Peeling	/'X3'	Woods	wite
	1891		0.16	5.	S.E. WINDOW FRAMES	Chipped Peeling		wood	white
	1892	ļ <u>.</u>	0.3	5-	BASEMENT WINDOW FOR	Intact Cracked		WOOD	white
	1893	2.9		5.	S.W. WINDOW FROMP	Chipped Peeling Intact Cracked	1"x 21	wood	white
	1894	 	0.00	<u>S.</u>	S.W. WINDOW FRAMES	Chipped Peeling		WOODS	white
	1895		0.9	ω .	CADLE Shingles	Chipped Peeling		wood	white

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.

Contractor's Quality Control Representative



Daily Quality Control Report **VB/I-70** Lead Based Paint Assessment

Date: 07-18-06

Property Location 4463

Type and Location of Tasts Property Proper

Type an	d Location of		ormed and	Results					
· 战。[6] 方。 · ·	gita atemiskog e		ing only	political an	The marginary of the captible	्रिश्नावीस्त्राध	्रम्युक्तान् संस्थ्यत् । ।	ajnoslijin.	(dija ka
2447	1896	1.5		W.	window Sill GAAL		2"x3'	WOOD	white
	1897	3.3		ω.	FASCIA GABLE	Intact Charkedo Chipped Peeling	4"× 6'	WOOD	white
	1898		0.04	w·	FASCIA Dehing GUTTE	Intact Cracked		wood	white
	1899		0.07	w.	N.W. wiNSOW Si			Wood	white
	1900		0.01	N.	FASCIA	Intact Cracked Pecling		abox	white
	1901	2.9	' -	N.	N.E. WINDOW FAMI	Intact Cracked Chipped Peeling		1000	white
	190>	1.5		N.	WAII	Chipped Peeling	51X/	Brick	whire
	1903		0.00	E·	BACK HOOSE pouch	Intact Cracked Chapter Pecling Intact Cracked		wood	Res
	1904		0.0	E.	pouch RAFRED TAILS BAN	Intact Cracked	<u></u>	WOOD	white
	1905		002	E.	posch Soffit BACKHO	Intact Cracked Chipped Peeling Intact Cracked		10001	white
	1906		0.03	6.	0 100 1000	OSe Empree Peeling		Bejck	white
	1907	2.8		E.	Roof soffit Book	Intact Cracked Chippers Pecling Intact Cracked	1'x7'	woon	white
	1908		0.08	<u>s.</u>	COANER BONED SE. HO			Wood	white
	1909		0.00	ے کے	GARK TRIM DOMAN	Chipped Peeling		10000	whire
	1910	 	0.12	S-	GAAR SOFFIT	enipped Pecling		WOOD	white
	1911	ļ	01/2	5-	GABLE VEWT DOO			W0015	white
	1912	 	0.06	5.	SOUTH FEWCE	Shipped Peeling		wood	white
	1913	1	0.02	N.	GARAGE WALL	Chipped Peeling		RRICK	white

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.

Contractor's Quality Control Representative



Daily Quality Control Report **VB/I-70** Lead Based Paint Assessment

Date: 07-18-66

Property Location 4463 C


Type ar	nd Location of	Tests Per	formed and	l Results					
् वेदिवृद्धानु । अद्योग	े अमेरिक और कि के बेहिल्या इंग्रिक	自由的 以为	ik ngd Tangkeya	ephsonon.	ી. ગામાં કરવા મન્યા મુદ્દારા વા મીન	<u>ૄૼૺઌ૽ૺઌ૽૽ઌ૽</u> ૽ૡ૽	्राकृतार महिल्ला । प्रा	smortific	(e[s]).
2447	1914		0.08			Intact Cracket Chipped Peeling Intact Cracket		(009)	white
	1915		0.24	B:	GARAGE DOOR FRANCE GARAGE DOOR FRANCE	Intact Cracked		wood	Red
	1916	2.9.		E.	GARAGE DOOR	Intact Cracked	21/21	wood	white
					,	Intact Cracked Chipped Peeling			
						Intact Cracked Chipped Peeling			
						Intact Cracked Chipped Peeling Intact Cracked			
			ļ	ļ		Chipped Peeling Intact Cracked			
			ļ			Chipped Peeling Intact Cracked			
			 			Chipped Peeling Intact Cracked	ļ		
						Chipped Peeling Intact Cracked			-
						Chipped Peeling Intact Cracked			
 			ļ <u> </u>	 		Chipped Peeling Intact Cracked			
						Chipped Peeling Intact Cracked			
		<u> </u>	 	<u> </u>		Chipped Peeling Intact Cracked Chipped Peeling	-		
						Chipped Peeling Intact Cracked Chipped Peeling			
			<u> </u>			Intact Cracked Chipped Peeling			
						Intact Cracked Chipped Peeling			

I certify that the above report is complete and correct and that I, or my authorized representative, have inspected all work performed this day and have determined that all materials, equipment, and workmanship are in strict compliance with the plans and specifications, except where noted herein.

Contractor's Quality Control Representative

PROPERTY INFOR	RMATION		DECISION CRITE	RIA
Property ID:	2447		Target Property?	Yes
House Number:	4463		Soil Sampled?	Yes
Street:	CHEROKEE ST		Removal Required?	Yes
Address:	4463 CHEROKEE ST	Find Record	Removal Complete?	2004
Unit:				
ZIP Code:	80216	1	SOIL SAMPLE RI	ESULTS
Neighborhood:	GLOBEVILLE	4	Phase 3A	
Zone:		J	Arsenic Decision Value	e 87
			Lead Decision Value	311
OWNER INFORMA	ATION			•
Owner Name:	ANDREW M PADILLA	-		
Mailing Address:	4463 CHEROKEE ST			
Mailing City State Zip:	Denver, CO80216		OTHER SAMPLE	RESULTS
			Media Description	
			Arsenic	
			lend [

Doesh







- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact Jennifer Chergo, EPA, at (303) 312-6601.

	my properties 1939 303-586-0727 1732 pager	☐ I do not grant acc	ess to my properties
Le un De la) 1-12-04 Date	Signature	Date
] I would like to b	pe present during any sampli	ng that is required.	







- Remover obstruciónes que incluye botes, remolque, vehículos, jugetes de niños, montones de madera, casas de perros, etc.
- Remover de bulbos de flores, o otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener reemplazo de vegetación, incluso la aplicación de fertilizante, como es necesario subsecuente de la riega inicial por el EPA, a menos que regando está restringido por la Junta de Agua de Denver.
- Permanecer por la guia de Salud y Seguridad proveido por el EPA;
- Si la propiedad está rentado, asiste el EPA a obtener la aprobación del inquilino para acceso a la propiedad a llevar a cabo el trabajo, si el EPA está inhábil a obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad incluyendo los areas exterior y interior de edificios.

ACUERDO A NO INTERFERIR

rabajo hecho, o el ec acciones en respecto	luipo usado a llevar de la usa de dicho pnarios o el medio a	ferir o meterse en cua de cabo los actividade propiedad que podría mbiente, o permitir otra	s, o hacer cualquier arriesgar la salud o
Si tiene preguntas so (303) 312-6601.	bre este programa,	por favor contacta Je	nnifer Chergo, EPA,
☐ Si yo permito acceso	a mi propiedad	☐ No permito acce	so a mi propiedad.
Firma .	Fecha	Firma	Fecha
☐ Me gustaría ser pres	sento durante de cual	quier colleción de mues	tras.

Property Access Checklist

Property ID: 2447		. ==	STARTED ON://_		
Property Address: 4463 Chero	nce St	☐ WORK	COMPELTED ON:/_/_		
Property Owner: Andrew Page	lilla	Property R	enter:		
Mailing Address:		Home Phon	ie:		
4463 Cherokees	5 (-	Fax:			
		Cell/Pager:			
Home Phone: 303 433-093	9	Additional	Information:		
Fax:					
Cell/Pager: 303 580-0727					
Notification Letter	Sent: 12	115/23	By: A. James		
Access Agreement	Signed: 1	112/04	By: A. Padilla		
Restoration Agreement	Signed: Z	116104	By: A. Padilla		
Topsoil Sampling (if applicable)	/	_/	Ву:		
Disposal Sampling (if applicable)	/		By:		
Garden Sampling (if applicable)			By:		
Utility Clearance	Called: / /		By:		
Video/Photos (Before)	On: 2 / 16/64		By: T. myers		
☐ Video/Photos (During)	On://		By:		
☐ Video/Photos (After)	On://		Ву:		
☐ Video/Photos (30-Day)	On://		By:		
Property Completion Agreement	Signed://		By:		
☐ Final Report	Issued://		By:		
Air Monitoring (as applicable)					
Community Crew On:// By:					
Results:					
Community Crew On:	//_	By:			
Results:					
Community Crew On:	//_	By:			
Results:					

Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 2447	
Property Address: 4463 Cherchel St	
Owner: Andrew Padilla	
Phone: 303 580 -0727	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:
BBQ Grill in back
Item:
Hem:
Item:
Trash cans in back
Item:
Wooden Planters in back
Item:
<u> </u>



· Project Resources Inc.

Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

Item:	Some,
	lood ties in back pard
Item:	Some Sod ties in back yard SEE Swetch
item:	
Item:	
ltem:	
item:	
item:	
ltem:	
Item:	
Item:	
ltem:	
item:	
Item:	
Item:	
Item:	



Project Resources Inc.

Items To Be Removed By Contractor During Remediation And Replaced (Use additional sheets as necessary)

tem:	
Clothes line Poles	
tem:	
CICTURES line POIRS tem: Any fence + anen down for acceptem:	<u>.</u> S
tem:	
tem:	
tem:	
tem:	
A	\dashv
tem:	
tem:	
em:	
tem:	
em:	\dashv
em:	
em:	一
	j
em:	\exists
em:	\neg
em:	
	1

Landscape Inventory (Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	2745	Square Feet	
Number of trees > 2 inch trunk diameter	4		
Number of trees < 2 inch trunk diameter	Ø		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	V/A		Zones:/A Heads:/A Control Valves://A
Number of and total size of all gardens / flower beds.	# Of Beds:		Ft ² Of Beds:/A
Attach a sketch of relative sizes and locations.	# Of Gardens:		Fr ² Of Gardens:

Project Besources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Store this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft2 Of Beds To Be Replaced With Certificate:
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be piaced by the contractor.	N/A	Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.	2342	SF	Total Ft ² Of Sod To Be Laid: <u>2342</u>
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Ft ² :	SF	Sod: \sqrt{A} Brown Mulch: \sqrt{A} Red Mulch: \sqrt{A}
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch:	SF	Red:

Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock:	SF	Medium:/A
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover:		NA

Additional Comments / Instructions:

See sketch - Be careful on back Side of house there is an old entrance door that leads to basement that is Durriad and can not be seen. Hand dig the area Surrounded by rail ties.

Additional Comments / Instructions Continued:
house Take a laint of
leave for coner
Check the box if Owner does not want PRI to document interior foundation walls and possible pre-existing damage. By checking this box PRI is not responsible for any damage done to the interior of house, including foundation cracks or fissures.
☐ I agree ☐ I do not agree ☐ I do not agree
Owner's Signature Date Contractor's Signature Date

Page 7



Project Besources Inc.

Property Completion Agreement

This agreement documents the completion of remedial activities performed on my property. My signature will designate that I am satisfied with the restoration of my property, and that no items are in questions, now, or at any time in the future, except those items listed below, if any.

120 41 /m / /am 2 4/29/0
following reinstallation by contractor
I agree that the sprinkler system is working properly
I do not agree restoration is completed .
I agree restoration is completed, except as noted
exiquenti
O'hewise all
Additional Comments: Place have Ricardo come and water mere after Otherwise all Macrew Jayson, Maria, George have been excellent!
Theuse have RICARdo come and water were atten
Additional Comments:
Item:
Restoration Items in Question:
Phone: 303-433-0939 - Pager 3035800727
Owner: (Indraw Padilla
Property ID: 2447 Property Address: 443 Charles by

CRBC 2001 Blake Street Denver, CO 80205-2000





VB/I-70 Command Post 10 55th Avenue Denver, Colorado 80216

TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1051773

	DOGGMENT NOMBER.
SI	TE NAME: VASQUEZ BOULEVARD AND I-70
DO	OCUMENT DATE: 01/12/2004
Dı	DOCUMENT NOT SCANNED ue to one of the following reasons:
	PHOTOGRAPHS
	3-DIMENSIONAL
	OVERSIZED
V	AUDIO/VISUAL
	PERMANENTLY BOUND DOCUMENTS
	POOR LEGIBILITY
	OTHER
	NOT AVAILABLE
	TYPES OF DOCUMENTS NOT TO BE SCANNED (Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody
DC	CUMENT DESCRIPTION:
	1 - DVD OF PROPERTY VIDEO, PROPERTY #2447 1 - PROPERTY DATA CD